



# RAIL ENGINEERING BUSINESS UNIT



## **RAIL ENGINEERING BUSINESS UNIT**

### **Development Timeline**





### REFERENCES

#### Project which are in the process Year 2021

#### • •

Project: Maintenance Contract Repairing the structure of diesel multiple unit of THN, NKF, ATR, DAEWOO for 12 months

Customer: State Railway of Thailand (SRT)

Location: Makkasan, Bangkok, Thailand

Scope of work:Procurement of labor, tools, equipment and repairs



#### Process

- Supply skilled labor
- Provide tools
- Repair work as specified by the employer

#### Warranty

- 1 year after the inspection committee accepts the work


## **RAIL ENGINEERING BUSINESS UNIT**

#### The project that has contributed to SRT Year 2017

Re condition Tube Suspension for Electric Diesel Locomotive GEA

Bogie frame which has been tested for repair and used for 3 years





4554

## **RAIL ENGINEERING BUSINESS UNIT**

#### The project that has contributed to SRT Year 2018

Re condition Bogie Frame for Electric Diesel Locomotive ALSTHOM

#### Damaged bogie frame waiting for amortization



Bogie frame which has been tested for repair and used for 2 years



Compared to the new product from South Korea



## REFERENCES

#### The project that has contributed to SRT Year 2020

#### • •

Project: Re-condition of wheel and axle of Alstom locomotive

Customer: State Railway of Thailand (SRT)

Location: Makkasan, Bangkok, Thailand

Scope of work: Material supply / Metal spray / Machining and grinding

#### Re-condition of wheel and axle of Alstom locomotive for 60Set

Process

- prepare the surface
- spray
- Machining & Grinding Quality
- Surface hardness< 250 HB
- Surface roughness< 0.4 m.

Warranty

- 1 year after use or
- 15 months after delivery



### REFERENCES

#### • •

Project: Repairing Gas carriage No. 250029

# Customer: State Railway of Thailand (SRT)

Location: BangSue, Bangkok, Thailand

Scope of work: Repair and inspection NDT

#### The project that has contributed to SRT Year 2021

## Repairing Gas carriage No. 250029 Repair and inspection NDT

Warranty

- 1 year after the inspection committee accepts the work

